

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 06/04/2018 11:40 PM		4. Date/Time of Death 06/05/2018 06:06 PM		5. Fatal Case No 5				
6. Mine Information :												
a) Mining Company Name Carter Roag Coal Company			b) Mine Name Morgan Camp Mine			c) Parent of Mining Company Metinvest B V						
7. Mine Location :		a) City Helvetia		b) County Randolph		c) State WV		8. Mine ID Number: 46-08656		9. Union: NO		
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND			11. Number of Mine Employees:		a) Total 147	b) Underground 147	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other		
12. Contractor Name:						13. Union		14. Contractor ID Number:				
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code				
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:						
a) Mine Employees: 65		b) Contractor Employees:				a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident									20. Mining Height:			
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches		
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		5	9				
21. Nonfatal Injuries:			22. Fatal Injuries:			1						
23. Victim Information :												
a) Name Ronald Taylor					b) Age 43							
c) Regular Job Title: Shuttle Car Operator				d) Activity at Time of Accident: Exiting mine via personnel carrier				<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days				
a) Total:	10	0	0	b) at the mine:	0	10	0	c) at activity (23d)	10	0	0	d) with Contractor
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.: (304) 924-6757						

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
On June 4, 2018, at approximately 11:40 p.m., a diesel-powered personnel carrier travelled over a roof jack lying in the roadway. The roof jack was propelled into the passenger's compartment and struck the victim's head. The victim was flown to a hospital where he died as a result of his injuries.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Wallace Auto Parts & Service				29. Model: DUV-13-2-111					
30. District: C0300 Morgantown		32. Field Office: Bridgeport WV				33. Event Number: 6278652			
34. Accident Investigator: Jeffrey Channell				35. MSHA Person Notified: Gregory Fetty		Date 06/05/2018		Time 01:15 AM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Carlos T. Mosley				Date 06/05/2018			
38. Reason For Amendment:									